

XR17V35x Errata

Revision History

Document No.	Release Date	Change Description
202ER01	June 29, 2022	Added:
		 "Output Voltage on the VCC12 Supply Pins" section.
202ER00	April 22, 2022	Initial release.

Table of Contents

Introduction		
Erra	ıta	.1
	Potential OS Hang or Crash when XR17V35x is in L1 or L0s & L1 Entry	.1
	Output Voltage on the VCC12 Supply Pins	.1

Introduction

This errata documents the known bugs in the XR17V35x device family.

Note: XR17V35x refers to the XR17V352, XR17V354, and XR17V358 devices.

Errata

Potential OS Hang or Crash when XR17V35x is in L1 or L0s & L1 Entry

Description: The XR17V35x can exhibit incorrect behavior when operating in ASPM L1 entry or L0s & L1 entry. This can result in OS not able to correctly bootup or system hang/crash during data transfer.

Workaround: Set ASPM to L0 Entry or Disabled under BIOS.

Output Voltage on the VCC12 Supply Pins

Description:	There is approximately 1.9V on the VCC12 supply pins when the XR17V35x powers up. The 1.9V may enable the over-voltage protection of an external 1.2V regulator and prevent it from providing the 1.2V required for the 1.2V core of the XR17V35x.
Audience:	Only customers who use an external regulator may be affected. Customers who use the internal buck regulator output for the VCC12 pins are not affected.
Root Cause:	Antenna diodes are typically used to avoid charge build-up during the manufacturing process. This is typically used on I/Os and internal signals with long signal traces. An antenna diode was inadvertently added on the VCC33A pin (3.3V supply for the analog PHY) to VCC12 during the layout of the device. There is also an ESD diode on the VCC12 pin to GND. When there is no signal on the VCC12 pin, these 2 diodes form a voltage divider that results in a voltage of approximately1.9V.
Severity-Low	There is no reliability issue or concern related to the antenna diode. The only side effect of the diode is that there will be approximately 4mA flowing through the antenna diode if 1.2V is applied to the VCC12 pins. However, this will not damage the antenna diode or the device.
Workaround:	For customers who are using an external regulator, the suggested work-around is to add a 250 ohm pull-down resistor on the VCC12 pin. This pull-down resistor will bring the output voltage down to approximately 1.2V and this should allow the external regulator to turn on to provide 1.2V to the VCC12 pins. This work-around is not required by customers who are using the internal buck regulator.



Corporate Headquarters: 5966 La Place Court, Suite 100 Carlsbad, CA 92008 Tel.: +1 (760) 692-0711 Fax: +1 (760) 444-8598

www.maxlinear.com

The content of this document is furnished for informational use only, is subject to change without notice, and should not be construed as a commitment by MaxLinear, Inc. MaxLinear, Inc. assumes no responsibility or liability for any errors or inaccuracies that may appear in the informational content contained in this guide. Complying with all applicable copyright laws is the responsibility of the user. Without limiting the rights under copyright, no part of this document may be reproduced into, stored in, or introduced into a retrieval system, or transmitted in any form or by any means (electronic, mechanical, photocopying, recording, or otherwise), or for any purpose, without the express written permission of MaxLinear, Inc.

Maxlinear, Inc. does not recommend the use of any of its products in life support applications where the failure or malfunction of the product can reasonably be expected to cause failure of the life support system or to significantly affect its safety or effectiveness. Products are not authorized for use in such applications unless MaxLinear, Inc. receives, in writing, assurances to its satisfaction that: (a) the risk of injury or damage has been minimized; (b) the user assumes all such risks; (c) potential liability of MaxLinear, Inc. is adequately protected under the circumstances.

MaxLinear, Inc. may have patents, patent applications, trademarks, copyrights, or other intellectual property rights covering subject matter in this document. Except as expressly provided in any written license agreement from MaxLinear, Inc., the furnishing of this document does not give you any license to these patents, trademarks, copyrights, or other intellectual property.

MaxLinear, the MaxLinear logo, any MaxLinear trademarks (MxL, Full-Spectrum Capture, FSC, G.now, AirPHY, Puma, and AnyWAN), and the MaxLinear logo on the products sold are all property of MaxLinear, Inc. or one of MaxLinear's subsidiaries in the U.S.A. and other countries. All rights reserved. Other company trademarks and product names appearing herein are the property of their respective owners.

© 2022 MaxLinear, Inc. All rights reserved.