



# Product Change Notice

PCN Number: 14-0520-01  
Issue Date: 4-JUNE-2014

**Exar Corporation**

[www.exar.com](http://www.exar.com) | Support: [customersupport@exar.com](mailto:customersupport@exar.com)

## PRODUCTS AFFECTED:

|              |                 |              |                 |
|--------------|-----------------|--------------|-----------------|
| SP3232EUCA-L | SP3232EUCA-L/TR | SP3232EUEA-L | SP3232EUEA-L/TR |
| SP3232EUCN-L | SP3232EUCN-L/TR | SP3232EHEY-L | SP3232EHEY-L/TR |
| SP3232EUCY-L | SP3232EUCY-L/TR | SP3232EHCY-L | SP3232EHCY-L/TR |
| SP3232EUEY-L | SP3232EUEY-L/TR |              |                 |

## CHANGE CATEGORY:

- |  |   |   |
|--|---|---|
| <input type="checkbox"/> Material  | <input checked="" type="checkbox"/> Process | <input type="checkbox"/> Package          |
| <input type="checkbox"/> Design  | <input type="checkbox"/> Datasheet          | <input type="checkbox"/> Packing/Shipping |
| <input checked="" type="checkbox"/> Other: Alternate Foundry & Assembly Site |   |   |

## DESCRIPTION OF CHANGE:

- Qualification of alternate foundry site, TSMC, using 0.25um CMOS process.
- Qualification of alternate assembly site, Carsem, for SOIC and TSSOP packages.
- Qualification of alternate assembly site, Greatek, for SSOP packages.

## IMPACT OF CHANGE:

There is no change to product form, fit or function.

**TARGET IMPLEMENTATION DATE:** 4-SEPTEMBER-2014

Please contact customer support ([customersupport@exar.com](mailto:customersupport@exar.com)) for sample date availability or qualification data

### PROPRIETARY INFORMATION

THIS DOCUMENT CONTAINS INFORMATION WHICH IS THE EXCLUSIVE PROPERTY OF EXAR CORPORATION. DISTRIBUTION, REPRODUCTION OR USE BY OTHERS IS NOT PERMITTED WITHOUT THE EXPRESS WRITTEN AUTHORIZATION OF EXAR CORPORATION.