



# Product Change Notice

PCN Number: 14-0626-01  
Issue Date: 21-AUGUST-2014

Exar Corporation

[www.exar.com](http://www.exar.com) | Support: [customersupport@exar.com](mailto:customersupport@exar.com)

**PRODUCTS AFFECTED:**

|             |                |               |
|-------------|----------------|---------------|
| XRP6274EH-F | XRP6274EHMTR-F | XRP6274EHTR-F |
| XRP6275EH-F | XRP6275EHMTR-F | XRP6275EHTR-F |
| XR71211EH-F | XR71211EHMTR-F | XR71211EHTR-F |

**CHANGE CATEGORY:**

|  |                                    |   |
|--|------------------------------------|---|
| <input type="checkbox"/> Material          | <input type="checkbox"/> Process   | <input type="checkbox"/> Package          |
| <input checked="" type="checkbox"/> Design | <input type="checkbox"/> Datasheet | <input type="checkbox"/> Packing/Shipping |
| <input type="checkbox"/> Other:            |                                    |   |

**DESCRIPTION OF CHANGE:**

Metal mask changed to improve trim range and yield. There is no change to the product datasheet.

**IMPACT OF CHANGE:**

No change to product form, fit or function

**TARGET IMPLEMENTATION DATE:** 21-NOVEMBER-2014

Please contact customer support ([customersupport@exar.com](mailto:customersupport@exar.com)) for sample date availability or qualification data

**PROPRIETARY INFORMATION**

THIS DOCUMENT CONTAINS INFORMATION WHICH IS THE EXCLUSIVE PROPERTY OF EXAR CORPORATION. DISTRIBUTION, REPRODUCTION OR USE BY OTHERS IS NOT PERMITTED WITHOUT THE EXPRESS WRITTEN AUTHORIZATION OF EXAR CORPORATION.